

## Service Bulletins and Recall Notices



### Bulletin

DATE. January 30,2004  
TO: All Chevron Distributors  
SUBJECT. Hose Trough Maintenance

Chevron recommends that in severe winter and weather conditions that the hose trough be kept free of ice and snow. If enough snow and ice accumulates and freezes in the trough it may cause the system to work incorrectly. Physically cleaning the trough for excessive build up above the divider can prevent this. This should be done by looking in the end of the trough that the build up is not above the divider. By simply cleaning out any excess ice, snow or debris the system should not have any trouble.

The hose trough will work with some snow build-up, but there is a point at which too much snow will render the divider so that the hoses will not track properly.